

Recalls and safety alerts

[Home](#) > [Recalls & alerts](#)
[Share](#) > [Contrast](#) > [Print](#)

DVI Lighting Inc. recalls semi-flush mounted medium base luminaires intended for use with maximum two 100 watt "Type A" lightbulbs

[Report a Concern](#)

Starting date: March 1, 2017
Posting date: March 1, 2017
Type of communication: Consumer Product Recall
Subcategory: Electronics
Source of recall: Health Canada
Issue: Electrical Hazard
Audience: General Public
Identification number: RA-62426

- [Affected products](#)
- [What you should do](#)

Affected products

Semi-flush mounted medium base luminaires intended for use with maximum two 100 watt "Type A" lightbulbs

Product description

The recalled products involve the following 10 luminaires:

Model/SKU	Finishes	UPC	Model/SKU	Finishes	UPC
Devonshire DVP7411	NI-OP	61467007193	Milan DVP5304	BN-SW	61467018670
	ORB-BS	61467009241		CH-SD	61467021298
	ORB-OP	61467016119		MO-BTL	61467018793
	PW	61467744654		MO-SW	61467029508
				ORB-BB	61467025883
Devonshire DVP7430	NI-OP	61467016706	Luna DVP5211	CH-NB	61467018618
	ORB-BS	61467015952		CH-WPM	61467018571
	ORB-OP	61467016270			
	PW	61467015969			
Longbow DVP2015	ORB-OP	61467023612	Moondust DVP2404	CH-CRY	61467026347
Princeton DVP2111	CH-OP	61467036926	Yorkville DVP8011	VB	Unknown
	GR-OP	61467036933		CH-OP	
King Edward DVP8212	VB	Unknown	Richmond DVP8312	ORB-OP	61467023087
	ORB			PW-OP	61467023070

Hazard identified

The luminaire wiring may overheat if the lightbulbs are too close to or in contact with the wiring, resulting in a possible short-circuit and potential fire.

Some products were not assembled with an approved 2x100 watt medium base cluster. The non-approved cluster may allow the wires to either come into contact with the light bulbs or violate the UL/CSA standard of coming within 2 inches of the bulbs. This can cause overheating of the luminaire wiring.

As of February 2017, the company has received one report of short-circuiting in Canada, and no report of injury.

Health Canada has not received any reports of consumer or complaints related to the use of these products.

Number sold

Approximately 48,000 units of the affected products were sold in Canada.

Time period sold

The affected products were sold between 2003 and 2016 at various retailers and online sellers.

Place of origin

Manufactured in China.

Companies

Distributor	DVI Lighting Inc. Concord Ontario CANADA
Manufacturer	Bradal Lighting Zhongshan, Guandong CHINA
Manufacturer	Corona Foshan Metalworking Pingzhou, Nanhai, Foshan CHINA
Manufacturer	Guangdong Huali Metalworking (out of business) Pingzhou, Nanhai, Foshan CHINA

Images (select thumbnail to enlarge)



What you should do

Consumers should immediately stop using the luminaires and contact DVI Lighting Inc. at customerservice@dvi.lighting or visit dvilighting to identify if your luminaire is affected.

Consumers can consult the [website](#) to obtain a QR code or view the Youtube instructional [video](#).

For more information, consumers can view the Intertek public notice on their website.

Please note that the Canada Consumer Product Safety Act prohibits recalled products from being redistributed, sold or even given away in Canada.

Health Canada would like to remind Canadians to report any health or safety incidents related to the use of this product or any other consumer product or cosmetic by filling out the [Consumer Product Incident Report Form](#).

This recall is also posted on the [OECD Global Portal on Product Recalls website](#). You can visit this site for more information on other international consumer product recalls.

Date modified: 2017-03-01