

## Recalls and safety alerts

Home > Recalls & alerts

>  Share >  Contrast >  Print

### Horizon Hobby recalls Dynamite 40-Amp FWD REV Brushed ESC in various remote ECX controlled vehicles

Report a Concern

<b>Starting date:</b>	April 25, 2017
<b>Posting date:</b>	April 25, 2017
<b>Type of communication:</b>	Consumer Product Recall
<b>Subcategory:</b>	Hobby/Craft Items, Toys
<b>Source of recall:</b>	Health Canada
<b>Issue:</b>	Burn Hazard, Fire Hazard
<b>Audience:</b>	General Public
<b>Identification number:</b>	RA-62324

- [Affected products](#)
- [What you should do](#)

#### Joint recall with Health Canada, the United States Consumer Product Safety Commission (US CPSC) and Horizon Hobby

#### Affected products

### Dynamite 40-Amp FWD REV Brushed Electronic Speed Control in various ECX remote controlled vehicles

#### Product description

This recall involves the Dynamite 40-Amp FWD REV Brushed ESC – DYNS2201. The controllers are installed in the ECX 1/10 LiPo Circuit, Ruckus and Torment models of the following remote-controlled vehicles:: ECX03130T1, ECX03130T2, ECX03131T1, ECX03131T2, ECX03133T1, ECX03133T2, ECX03154. The ESC measures 5 centimetres length by 3 <sup>3/4</sup> centimetres width. The model numbers can be found on the product box or in the owner's manual for each vehicle. The model vehicles measure about 18 inches in length and 12 inches in width and are hobby grade remote control models for ages 14 and up.

#### Hazard identified

The vehicle's electronic speed control (ESC) can fail and short circuit, posing a fire hazard.

As of April 25, the company has received 3 reports of ESCs that caught fire in Canada, and no reports of injuries.

In the United States, Horizon Hobby has received 19 reports of the ESC in the model truck and cars catching fire. No injuries or property damage has been reported.

**Number sold**

Approximately 540 units of the affected products were sold in Canada and approximately 18 600 were sold in the United States.

**Time period sold**

The recalled products were sold from October 2016 to December 2016 in both Canada and the USA.

**Place of origin**

Manufactured in China.

**Companies**

**Distributor**

Horizon Hobby, LLC  
Champaign  
Illinois  
UNITED STATES

**Manufacturer**

Shenzhen Shen's Tongchuang Aeronautic Model Co Ltd.  
Shenzhen  
CHINA

Images (select thumbnail to enlarge)

rge)





## What you should do

**Consumers should immediately stop using the remote controlled vehicles and contact Horizon Hobby for repair or refund.**

For more information, consumers can contact Horizon Customer Service phone number is 800-338-4639 Monday to Friday 8:00 a.m. to 5:30 p.m. CST or [email](#).

Consumers may view the release by the US CPSC on the [Commission's website](#).

Please note that the Canada Consumer Product Safety Act prohibits recalled products from being redistributed, sold or even given away in Canada.

Health Canada would like to remind Canadians to report any health or safety incidents related to the use of this product or any other consumer product or cosmetic by filling out the [Consumer Product Incident Report Form](#).

This recall is also posted on the [OECD Global Portal on Product Recalls website](#). You can visit this site for more information on other international consumer product recalls.

**Date modified:** 2017-04-25